

RACH timing




Fig. 1





Fig. 2

$$T_{AICH}=0$$

Fmod3	A=0 (000)	A=1 (001)	A=2 (010)	A=4 (100)
0	-	0, 3, 6	1, 4, 7	2, 5
1	-	1, 4, 7	2, 5	0, 3, 6
2	-	2, 5	0, 3, 6	1, 4, 7

Fig. 3

$$T_{AICH}=1$$

A=0 (0000)	A=1 (0001)	A=2 (0010)	A=4 (0100)	A=8 (1000)
-	0, 4	1, 5	2, 6	3, 7

Fig. 4

$$T_{AICH}=0$$

A=0 (000)	A=1 (001)	A=2 (010)	A=4 (100)
-	0, 3, 6, 9, 12	1, 4, 7, 10, 13	2, 5, 8, 11, 14

Fig. 5

$$T_{AICH}=1$$

$\Gamma \bmod 4$	A=0 (0000)	A=1 (0001)	A=2 (0010)	A=4 (0100)	A=8 (1000)
0	-	0, 4, 8, 12	1, 5, 9, 13	2, 6, 10, 14	3, 7, 11
1	-	1, 5, 9, 13	2, 6, 10, 14	3, 7, 11	0, 4, 8, 12
2	-	2, 6, 10, 14	3, 7, 11	0, 4, 8, 12	1, 5, 9, 13
3	-	3, 7, 11	0, 4, 8, 12	1, 5, 9, 13	2, 6, 10, 14

Fig. 6